

DMH PART CATCHER

For collecting series parts or heavy turned parts (e.g. PTFE parts) in order to prevent damage.

DETAILS	PART CATCHER
Air ¹	Compressed-air base supply
Min. part diameter	20 mm
Max. part diameter	130–150 mm

¹ Required compressed-air base supply